







Description	Progress		
MOD 3 Application	Scoping meeting held with DPIE		
Increase North Mine approved production	Consultation with EPA, BHCC and NSW Health Third party Air Quality Assessment and Human Health Diek		
production	Third party Air Quality Assessment and Human Health Risk Assessment finalised 20 October		
Increase No3 shaft ventilation fan output	Application report submitted to DPIE, 25 October		
Historic Heritage Management Plan	Submitted to DPIE and NSW Heritage Council for consultation and review		
Rehabilitation Strategy	Submitted to DPIE for review and consultation		
Rehabilitation Management Plan	To be developed upon acceptance of RS		
Mine Operating Plan (MOP), now Rehabilitation Management Plan (RMP)	Submitted to Resource Regulator, May 2021		




COVID-19 arriving in Broken Hill has affected operations with a large number of shifts lost due to COVID-19. Issues include, COVID-19 testing, flu like symptoms and interstate travel restrictions. To date we have kept it off site, although with some scares.

Controls re-implemented/implemented include:

- Mandatory wearing of masks on site.
- •Reinforcement of social distancing, where practicable.
- Reinforcement of personal hygiene practices.
- •Rapid antigen testing, for those who are determined to present a risk.
- Daily online COVID-19 Declaration which includes questions around:
 - Flu like symptoms.
 - NSW Health notified self or household member as close or casual contact.
 - Volunteered COVID-19 test and result
 - Travel to Broken Hill, in the past 14 days, dependent on worker's vaccination status they undergo rapid antigen test/s or 14 days site isolation.
- Daily online Work Contact Declaration, workers need to declare equipment operated and persons they had >10 minutes contact with during shift.





Truck Movements




















North Mine ROM





North Mine Water











North Mine Project - Community Concerns

Community complaints project to date:

Date	Via	Description	Response	
03/10/17	MCC	Noise from trucking	Complaint registered	
19/11/17	EPA	Noise from trucking	Instruction issued to workers, no trucking to surface after 19:00, and to limit in-pit tip so far as practicable on night shift	
10/04/18	EPA	Noise from equipment	Identified that noise was from shift-start equipment tramming to ramp. Reiterated no trucking to surface after 19:00. Investigating fitment of "surface running" mode on trucks and loaders to limit output on the surface. Investigating having db reading boards displayed so workers can understand potential community impacts	
20/04/18	EPA	Low drone noise	Noise monitoring in place, 4 level vent fans turned off to understand impact and if they are noise source.	
01/02/19	BDT	Water leak	Plasson fitting split on raw water poly pipe, repaired.	

How can community members contact Perilya?

- Mine Control Centre (08) 8088 8999 manned 24/7
- Mail PO Box 5001, Broken Hill NSW 2880
- Security Gate Southern Operations, Wentworth Road, Broken Hill



Next Three Months

Work to be undertaken in the next 3 months:

Description

Liaise with DPIE re MOD 3

Continue mining operations

KPI	October	November	December
Ore (t)	26,341	26,419	26,451
Headgrade PbZn	8.31	7.83	7.25
Development (m)	449.7	452.2	546.2
Decline (m)	91.7	88.8	91.7

